




Full Mission PSD Intensity Trends




Latest PSD Intensity Trends



# Full Mission PSD and Laser Temperatures




Full Mission Min/Max PSD and Laser Temperatures





PSD Laser Off Intensity


PSD0

PSD1




PSD0 Laser Off 1- $\sigma$  Noise


PSD0 Laser On 1- $\sigma$  Noise

PSD0 Laser Off 1- $\sigma$  Noise




PSD1 Laser On 1- $\sigma$  Noise


# PSD0 Laser On - Laser Off




# PSD1 Laser On - Laser Off




# PSD0 Laser Off Intensity




# PSD1 Laser Off Intensity



Laser Intensity vs Laser Housing Mean Temperatures



Laser Intensity vs Maximum Housing Temperatures



Laser Intensity vs Maximum Housing Temperatures

