







```
C:\WINDOWS\system32\cmd.exe
*** Make sure your treadmill is powered-up and USB Debugging is turned on ***
Enter treadmill IP address: fe80::21a:13ff:fed2:8d68
Pinging fe80::21a:13ff:fed2:8d68 with 32 bytes of data:
Reply from fe80::21a:13ff:fed2:8d68: time=298ms
Reply from fe80::21a:13ff:fed2:8d68: time=7ms
Reply from fe80::21a:13ff:fed2:8d68: time=8ms
Reply from fe80::21a:13ff:fed2:8d68: time=6ms

Ping statistics for fe80::21a:13ff:fed2:8d68:
    Packets: Sent = 4, Received = 4, Lost = 0 (0% loss),
    Approximate round trip times in milli-seconds:
        Minimum = 6ms, Maximum = 298ms, Average = 79ms

Waiting for 2 seconds, press a key to continue ...
```

	Uninstall-QZ-Companion	3/8/2024 12:28 PM	Windows Batch File	1 KB
	QZ-Companion-restart	3/8/2024 12:28 PM	Windows Batch File	2 KB
	QZ-Companion-simple	3/8/2024 12:28 PM	Windows Batch File	1 KB
	AdbWinApi.dll	3/8/2024 12:28 PM	Application extens...	96 KB
	AdbWinUsbApi.dll	3/8/2024 12:28 PM	Application extens...	62 KB
	QZ-Companion-MacOS	3/8/2024 12:28 PM	File	3 KB