

STEPPER
B- B+ A- A+
(On backside!)

**Part Fan
Solder
Jumper**

5V VFP 24V

**Hotend Fan
Solder
Jumper**

5V VFH 24V

Main Connector
(PCB socket, as
seen from front)

5V FH S0 TH1 TH0 HEAT 24V
GND FP S1 B- B+ A- A+

SWITCH1

GND
S1
5V

Part Fan
(On backside!)

FP
VFP

(On backside!)

Heater

HEAT
24V

**Ther-
mistor**

TH1
TH0

**Hotend
Fan**

FH VFH

SWITCH0

5V
S0
GND

Part Fan
(On backside!)

VFP
FP

(On backside!)

