



\*使用Servo 應用時, DC IN(+5C) 限定使用 5V 輸入

Diagram illustrating the locations of seven mounting holes (H1 to H7) on a rectangular plate. The holes are arranged in two rows: H1, H2, H3, and H4 in the top row, and H5, H6, and H7 in the bottom row. Each hole is represented by a black circle with a white center, and its label is to its right.

<b>Rev: A</b>
Id: 1/1