




# Accelerometer + Magnetometer sensor LSM303AGR





# Relative humidity and temperature sensor HTS221




# Pressure sensor LPS22HB




# Arduino UNO R3 Connectors




# I2C grove connector



# SWD



# Reset Button



# RF switch debug header



# RF & MCU Power Consumption Measurement



# Debug connect

