



Well Lit Barcode Configuration Sheet

Scan from left to right



Set Factory Defaults



DS4308-XD/XDH: Add Enter Key (Carriage Return/Line Feed)



Timeout Between Decodes, Different Symbols



4



0



Timeout Between Decodes, Same Symbol



4



0