








TITLE: Sheet_1		REV: 1.0
	Company: Your Company	Sheet: 1/1
	Date: 2023-10-05 Drawn By: Denjhang	







低音增强电容，未验证

R9/14改为4k7









TITLE: Sheet_1		REV: 1.0
	Company: Your Company	Sheet: 1/1
	Date: 2023-10-05	Drawn By: Denjhang



贴片5532可以国产，但是必须使用原装074C，LMV324

国产TL084C导致开机出现电源噪音，也不要LF347

TITLE: Sheet_2		REV: 1.0
	Company: Your Company	Sheet: 1/1
	Date: 2023-10-05	Drawn By: Denjhang



TITLE: Sheet_1		REV: 1.0
	Company: Your Company	Sheet: 1/1
	Date: 2023-11-12 Drawn By: Denjhang	