


Fix on next Revision
Missing + & - on LiPo connector
Need a stronger LDO (use CAT6219-330TDGT3)
Thicker tracks, remove pin 7 from Segger con
Three individual leds, one res network
Remove accel, adjust oled solder con position



Title		
Size	Number	Revision
C		
Date:	9/16/2016	Sheet of
File:	C:\Utility\...\Sheet1.1.SchDoc	Drawn By:

