



Dept.	Technical reference betrue3d.dk	Created by Morten Nielsen	Approved by 20-12-2017		
The 4x 2.5mm holes should be threaded m3		Document type Drawing	Document status Working copy		
		Title MotorShield Left	DWG No.		
			Rev.	Date of issue 30-01-2018	Sheet 1/1