

Machine Manual

Machine Name: Multi-Purpose Industrial Lathe

Specifications:

- Dimensions: 2m x 1m x 1.5m
- Weight: 800kg
- Power Requirements: 220V, 50Hz
- Operating Temperature: 10°C to 40°C

Instructions:

- Installation: Position on a flat surface; connect power and lubrication lines.
- Operation: Follow control panel instructions for startup, speed adjustment, and shutdown.
- Maintenance: Clean every 20 hours of use; inspect belts and gears monthly.

Safety Warnings:

- Wear safety goggles and gloves; keep clear of moving parts.

Troubleshooting:

- Machine not starting? Check power connection.
- Strange noise? Inspect belts for wear.