




Use M or Q rated parts.


receivers are always on





TODO: Make parts for Differential transmitter and receiver. Control transmitter with CS line.




get 2.5V reference also, if input voltages are low...




AGND and GND are connected



To Shutter Board





To Shutter Control



A choice of how to wire here

necessary? OK to float inputs here?



HI if any of faults 1 though 4 are LOW

