



FTS Service Report: Fuel Stick

for Serial Number:112233 serviced on:2023-11-28

NetSuite RMA#	NetSuite Customer Number	NetSuite Sales Order#	Jira Ticket
RMA-TESTFS	FTS TESTFS	SO-TESTFS	CST-TESTFS

Details of Service Preformed

Sensor Information

Serial Number	Module Serial Number	Model	Incoming Status
112233	009988	FS-3-R	Other (Desc. in Comments)

Incoming and Visual Inspections

Initial Checks	Failed - Explain in Comments
00-THS-3 Firmware Version	15
Visual inspection was completed?	True
Sensor was cleaned?	True
Tech notes on the incoming status	INCOMINGNOTES

Calibration and Servicing

Incoming Releative Humidity Test	Unable to Test
Incoming Temperature Test	Unable to Test
Sensor Require Repairs?	Repairs Preformed
Relaive Humidity Re-Calibrated?	Wafer Replaced - Recalibrated
Service Builentins Referenced?	Yes - See Comments
Active Current Test Passed?	True
Porex Filter Replaced?	True
Desiccant Packet Replaced?	True
Relative Humidity Passed Calibration?	True
Temperature Passed Calibration?	True
Cable-To-Module Screws Installed?	True
Dowel Replaced?	Yes

Other Service Details and Notes