



701 Brooks Ave South,  
PO Box 677  
Thief River Falls, MN 56701-0677  
USA

[www.digikey.com](http://www.digikey.com)  
Global Customer Support  
1-800-344-4539 or 218-681-6674

PO Acknowledgement 78315550  
USD \$

**Bill To:**  
ORLANDO YANEZ KINZEL  
SOCIEDAD ZIGBEE CHILE LTDA  
SOCIEDAD ZIGBEE CHILE LTDA  
SAN IGNACIO 908  
PUERTO VARAS  
PUERTO VARAS REG X 5550221  
CHILE

**Ship To:**  
HILDA LIZZI  
TRANS AIR SYSTEM  
SOC. ZIGBEE CHILE LTDA - ORLANDO YANEZ K  
8256 N. W 30 TH TERRACE, TLC3108  
DORAL, FLORIDA 33122-1914  
MIAMI FL 33122-1914  
USA

**Purchase Order:** 20221018\_01  
**Customer:** 3466748  
**Payment Terms:** Visa  
**Shipping Method:** FedEx Ground  
**Order Source:** INTERNET  
**Order Date:** 18-OCT-2022  
**Estimated Release Date:** 19-OCT-2022

**Buyer:**  
ORLANDO AUGUSTO YANEZ KINZEL  
SOCIEDAD ZIGBEE CHILE LIMITADA  
8256N. W 30TH TERRACE, TCL3108  
SOC.ZIGBEE CHILE LTDA-ORLABNDO YANEZ K  
FLORIDA DORAL 33122-1914  
CHILE

**Ship From:**  
DIGI-KEY ELECTRONICS  
701 BROOKS AVE. SOUTH  
P.O. BOX 677  
THIEF RIVER FALLS MN 56701-0677

Line Item	Ordered	Available Qty	Backordered Qty	Item Number/ Description	Unit Price USD \$	Amount USD \$
1	100	100	0	<b>PART:</b> WM18873-ND <b>CUST:</b> SPARE PARTS <b>MFG :</b> MOLEX, LLC / 0050375023 <b>C00 :</b> SOUTH KOREA ROHS3 COMP REACH UNAFFECTED 07-JUL-2017 <b>ECCN:</b> EAR99 <b>HTSUS:</b> 8536.69.8000 <b>DESC:</b> CONN RCPT HSG 2POS 2.50MM	0.09530	9.53
2	100	100	0	<b>PART:</b> 0050375033 <b>CUST:</b> SPARE PARTS <b>MFG :</b> MOLEX, LLC / 0050375033 <b>C00 :</b> SOUTH KOREA ROHS3 COMP REACH UNAFFECTED 07-JUL-2017 <b>ECCN:</b> EAR99 <b>HTSUS:</b> 8536.69.8000 <b>DESC:</b> CONN RCPT HSG 3POS 2.50MM	0.0132	1.32
3	20	20	0	<b>PART:</b> 0022057025 <b>CUST:</b> SPARE PARTS <b>MFG :</b> MOLEX CONNECTOR CORPORATION / 0022057025 <b>C00 :</b> CHINA ROHS3 COMP REACH UNAFFECTED 07-JUL-2017 Section 301 Tariff <b>ECCN:</b> EAR99 <b>HTSUS:</b> 8536.69.4040 <b>DESC:</b> CONN HEADER R/A 2POS 2.5MM	0.23900	4.78 0.48



701 Brooks Ave South,  
PO Box 677  
Thief River Falls, MN 56701-0677  
USA

[www.digikey.com](http://www.digikey.com)  
Global Customer Support  
1-800-344-4539 or 218-681-6674

PO Acknowledgement 78315550  
USD \$

Line Item	Ordered	Available Qty	Backordered Qty	Item Number/ Description		Unit Price USD \$	Amount USD \$
4	20	20	0	<b>PART:</b> 0022057035 <b>CUST:</b> SPARE PARTS <b>MFG :</b> MOLEX, LLC / 0022057035 <b>C00 :</b> CHINA ROHS3 COMP REACH UNAFFECTED 07-JUL-2017 Section 301 Tariff	<b>DESC:</b> CONN HEADER R/A 3POS 2.5MM  <b>ECCN:</b> EAR99  <b>HTSUS:</b> 8536.69.4040	0.22300	4.46
5	20	20	0	<b>PART:</b> 0022035035 <b>CUST:</b> SPARE PARTS <b>MFG :</b> MOLEX, LLC / 0022035035 <b>C00 :</b> SOUTH KOREA ROHS3 COMP REACH UNAFFECTED 07-JUL-2017	<b>DESC:</b> CONN HEADER VERT 3POS 2.5MM  <b>ECCN:</b> EAR99  <b>HTSUS:</b> 8536.69.4040	0.22000	4.40
6	500	500	0	<b>PART:</b> WM4561CT-ND <b>CUST:</b> SPARE PARTS <b>MFG :</b> MOLEX, LLC (VA) / 0502128000 <b>C00 :</b> MALAYSIA ROHS3 COMP REACH UNAFFECTED 07-JUL-2017	<b>DESC:</b> CONN SOCKET 24-30AWG CRIMP TIN  <b>ECCN:</b> EAR99  <b>HTSUS:</b> 8536.90.4000	0.02340	11.70
7	100	100	0	<b>PART:</b> YAG2478CT-ND <b>CUST:</b> SPARE PARTS <b>MFG :</b> YAGEO (VA) / RC0201FR-071K2L <b>C00 :</b> TAIWAN ROHS3 COMP REACH UNAFFECTED 08-JUL-2021	<b>DESC:</b> RES 1.2K OHM 1% 1/20W 0201  <b>ECCN:</b> EAR99  <b>HTSUS:</b> 8533.21.0030	0.01530	1.53
8	1	1	0	<b>PART:</b> YAG2274CT-ND <b>CUST:</b> SPARE PARTS <b>MFG :</b> YAGEO (VA) / RC0201FR-071K5L <b>C00 :</b> TAIWAN ROHS3 COMP REACH UNAFFECTED 08-JUL-2021	<b>DESC:</b> RES 1.5K OHM 1% 1/20W 0201  <b>ECCN:</b> EAR99  <b>HTSUS:</b> 8533.21.0030	0.10000	0.10
9	100	100	0	<b>PART:</b> P122851CT-ND <b>CUST:</b> SPARE PARTS <b>MFG :</b> PANASONIC ELECTRONIC COMPONENTS (VA) / ERJ-1GNF2371C <b>C00 :</b> JAPAN ROHS3 COMP REACH UNAFFECTED 19-JAN-2021	<b>DESC:</b> RES SMD 2.37K OHM 1% 1/20W 0201  <b>ECCN:</b> EAR99  <b>HTSUS:</b> 8533.21.0030	0.02470	2.47

All transactions with Digi-Key Electronics, including its subsidiaries and/or affiliates, are subject to Digi-Key's Terms of Use and Conditions of Order, available at [www.digikey.com](http://www.digikey.com).



701 Brooks Ave South,  
PO Box 677  
Thief River Falls, MN 56701-0677  
USA

[www.digikey.com](http://www.digikey.com)  
Global Customer Support  
1-800-344-4539 or 218-681-6674

PO Acknowledgement 78315550  
USD \$

Line Item	Ordered	Available Qty	Backordered Qty	Item Number/ Description	Unit Price USD \$	Amount USD \$
10	100	100	0	<b>PART:</b> YAG2581CT-ND <b>CUST:</b> SPARE PARTS <b>MFG :</b> YAGEO (VA) / RC0201FR-072K7L <b>COO :</b> TAIWAN ROHS3 COMP REACH UNAFFECTED 08-JUL-2021 <b>ECCN:</b> EAR99 <b>HTSUS:</b> 8533.21.0030 <b>DESC:</b> RES 2.7K OHM 1% 1/20W 0201	0.01530	1.53
11	100	100	0	<b>PART:</b> YAG2656CT-ND <b>CUST:</b> SPARE PARTS <b>MFG :</b> YAGEO (VA) / RC0201FR-073KL <b>COO :</b> TAIWAN ROHS3 COMP REACH UNAFFECTED 08-JUL-2021 <b>ECCN:</b> EAR99 <b>HTSUS:</b> 8533.21.0030 <b>DESC:</b> RES 3K OHM 1% 1/20W 0201	0.01530	1.53
12	100	100	0	<b>PART:</b> YAG2285CT-ND <b>CUST:</b> SPARE PARTS <b>MFG :</b> YAGEO (VA) / RC0201FR-073K3L <b>COO :</b> TAIWAN ROHS3 COMP REACH UNAFFECTED 08-JUL-2021 <b>ECCN:</b> EAR99 <b>HTSUS:</b> 8533.21.0030 <b>DESC:</b> RES 3.3K OHM 1% 1/20W 0201	0.01530	1.53
13	10	10	0	<b>PART:</b> YAG2655CT-ND <b>CUST:</b> SPARE PARTS <b>MFG :</b> YAGEO (VA) / RC0201FR-073K9L <b>COO :</b> TAIWAN ROHS3 COMP REACH UNAFFECTED 08-JUL-2021 <b>ECCN:</b> EAR99 <b>HTSUS:</b> 8533.21.0030 <b>DESC:</b> RES 3.9K OHM 1% 1/20W 0201	0.03700	0.37
14	100	100	0	<b>PART:</b> YAG2741CT-ND <b>CUST:</b> SPARE PARTS <b>MFG :</b> YAGEO (VA) / RC0201FR-075K1L <b>COO :</b> TAIWAN ROHS3 COMP REACH UNAFFECTED 08-JUL-2021 <b>ECCN:</b> EAR99 <b>HTSUS:</b> 8533.21.0030 <b>DESC:</b> RES 5.1K OHM 1% 1/20W 0201	0.01530	1.53
15	100	100	0	<b>PART:</b> YAG2780CT-ND <b>CUST:</b> SPARE PARTS <b>MFG :</b> YAGEO (VA) / RC0201FR-076K2L <b>COO :</b> TAIWAN ROHS3 COMP REACH UNAFFECTED 08-JUL-2021 <b>ECCN:</b> EAR99 <b>HTSUS:</b> 8533.21.0030 <b>DESC:</b> RES 6.2K OHM 1% 1/20W 0201	0.01530	1.53



701 Brooks Ave South,  
PO Box 677  
Thief River Falls, MN 56701-0677  
USA

[www.digikey.com](http://www.digikey.com)  
Global Customer Support  
1-800-344-4539 or 218-681-6674

PO Acknowledgement 78315550  
USD \$

Line Item	Ordered	Available Qty	Backordered Qty	Item Number/ Description		Unit Price USD \$	Amount USD \$
16	100	100	0	<b>PART:</b> YAG2353CT-ND <b>CUST:</b> SPARE PARTS <b>MFG :</b> YAGEO (VA) / RC0201FR-078K2L <b>COO :</b> TAIWAN ROHS3 COMP REACH UNAFFECTED 08-JUL-2021	<b>DESC:</b> RES 8.2K OHM 1% 1/20W 0201  <b>ECCN:</b> EAR99 <b>HTSUS:</b> 8533.21.0030	0.01530	1.53
17	100	100	0	<b>PART:</b> 311-10.0KMCT-ND <b>CUST:</b> SPARE PARTS <b>MFG :</b> YAGEO (VA) / RC0201FR-0710KL <b>COO :</b> TAIWAN ROHS3 COMP REACH UNAFFECTED 08-JUL-2021	<b>DESC:</b> RES 10K OHM 1% 1/20W 0201  <b>ECCN:</b> EAR99 <b>HTSUS:</b> 8533.21.0030	0.01530	1.53
18	25	25	0	<b>PART:</b> A1371-ND <b>CUST:</b> SPARE PARTS <b>MFG :</b> TE CONNECTIVITY AMP / 206434-1 <b>COO :</b> MEXICO ROHS3 COMP REACH NOT AVAILABLE 19-JAN-2021	<b>DESC:</b> CONN PLUG HSNQ MALE 8POS INLINE  <b>ECCN:</b> EAR99 <b>HTSUS:</b> 8538.90.6000	1.0904	27.26
19	100	100	0	<b>PART:</b> A1028-ND <b>CUST:</b> SPARE PARTS <b>MFG :</b> TE CONNECTIVITY AMP / 66570-3 <b>COO :</b> USA ROHS3 COMP REACH NOT AVAILABLE 19-JAN-2021	<b>DESC:</b> CONN PIN 18AWG GOLD SOLDER CUP  <b>ECCN:</b> EAR99 <b>HTSUS:</b> 8536.90.4000	0.03330	3.33
20	10	10	0	<b>PART:</b> 296-40576-1-ND <b>CUST:</b> SPARE PARTS <b>MFG :</b> TEXAS INSTRUMENTS (VA) / TCA9544APWR <b>COO :</b> MALAYSIA ROHS3 COMP REACH UNAFFECTED 25-JUN-2020	<b>DESC:</b> IC MULTIPLEXER 1 X 1:4 20TSSOP  <b>ECCN:</b> EAR99 <b>HTSUS:</b> 8542.39.0001	0.1590	1.59
21	3	3	0	<b>PART:</b> 161-LT1677IN8#PBF-ND <b>CUST:</b> SPARE PARTS <b>MFG :</b> ANALOG DEVICES INC / LT1677IN8#PBF <b>COO :</b> MALAYSIA ROHS3 COMP REACH UNAFFECTED 17-JAN-2022	<b>DESC:</b> IC OPAMP GP 1 CIRCUIT 8DIP  <b>ECCN:</b> EAR99 <b>HTSUS:</b> 8542.33.0001	0.7290	2.19



701 Brooks Ave South,  
PO Box 677  
Thief River Falls, MN 56701-0677  
USA

[www.digikey.com](http://www.digikey.com)  
Global Customer Support  
1-800-344-4539 or 218-681-6674

PO Acknowledgement 78315550  
USD \$

Line Item	Ordered	Available Qty	Backordered Qty	Item Number/ Description	Unit Price USD \$	Amount USD \$
22	10	10	0	<b>PART:</b> TC7660COA713CT-ND <b>CUST:</b> SPARE PARTS <b>MFG :</b> MICROCHIP TECHNOLOGY (VA) / TC7660COA713 <b>COO :</b> THAILAND <b>ECCN:</b> EAR99 <b>HTSUS:</b> 8542.39.0001 ROHS3 COMP REACH UNAFFECTED 12-JAN-2017	0.1600	1.60
23	25	25	0	<b>PART:</b> A105209-ND <b>CUST:</b> SPARE PARTS <b>MFG :</b> TE CONNECTIVITY AMP / 1-206062-7 <b>COO :</b> MEXICO <b>ECCN:</b> EAR99 <b>HTSUS:</b> 8538.90.8180 ROHS COMP	1.6500	4.13

Sales Amount	86.46
Tariff Amount	0.93
Total Sales and Tariff	87.39
Shipping charges applied	6.99
Total	94.38
USD \$	

General - WEB ORDER ID: 333291589

PLEASE DO NOT CHARGE INTERSTATE TAXES, THE USE AND FINAL DESTINATION OF THESE SPARE PARTS IS OUR COMPANY IN CHILE. SHIPMENTS TO CHILE ARE MADE BY OUR COURIER IN DORAL, FL (TRANS-AIR SYSTEM, INC.).

Your order may take 1-3 business days to ship due to peak order volumes combined with ensuring the health and safety of our team members due to Covid-19.