

Houston Power Savers

TACLB020326E

10222 Inwood Dr
Houston, Texas 77042
Office: (832) 968-0000
www.HoustonPowerSavers.com

INVOICE

Code: *code*
DATE: March 2, 2022
INVOICE # 01210302
FOR: *Service call*

David Lam
5714 Basswood Dale Dr
Houston, TX 77084
(713) 594-4941
delamhtex@sbcglobal.net

DESCRIPTION	AMOUNT
Checked drier vent exhaust	
service fee	\$ 127.00
-	
TOTAL	\$ 127.00

Make all checks payable to Houston Power Savers
If you have any questions concerning this invoice, Kenneth Longoria 713-3062694

THANK YOU FOR YOUR BUSINESS!

