

Houston Power Savers

TACLB020326E

10222 Inwood Dr
Houston, Texas 77042
Office: (832) 968-0000
www.HoustonPowerSavers.com

INVOICE

Code: iccf414
DATE: November 10, 2021
INVOICE # 00211110
FOR: New installation

Steve Hartwig
664 W Forest Dr
Houston, TX , 77079
(713) 962-9170
Schartwig@sbcglobal.net

DESCRIPTION	AMOUNT
Install new 5 ton evaporator slab coil M/N: 4MXCC009AC6HCA / S/N: 204520632M *vacuum time, ~1 hr *reseal openings with hardcast subtotal	\$ 3,275.00
Install new 100k BTU gas furnace M/N: A801X100CM5SCAA / S/N: 21346XL6JG *reseal openings with hardcast *new roofjack *new supply plenum *new heater stands *new double wall vent pipe *rewire controls to furnace subtotal	\$ 3,875.00
All new duct work *all new collars and dampers *15 bags of R8 flex subtotal	\$ 1,800.00
Pick-up/installation of 2 new media filters—325.00 ea *filters for upstairs and downstairs systems subtotal	\$ 700.00
Labor cost subtotal	\$ 975.00
For downstairs work: *remaining balance on original invoice—372.00 *added gas flex line and drip leg to furnace—700.00 subtotal	\$ 1,072.00
Note: 10 yr warranty on parts. 20 yr warranty on heat exchanger HPS Provides a 2 yr. labor warranty	
TOTAL	\$ 11,697.00

Make all checks payable to Houston Power Savers
If you have any questions concerning this invoice, Kenneth Longoria 713-3062694

THANK YOU FOR YOUR BUSINESS!