



Mouthpiece Reading Error Occurs During Operation phase
 -Cause: missed writing to EEPROM on MCA 5 times in a row
 -remove MCA to return to "insert mouthpiece" screen