



This 5V is from the PSLV, is not considered in the sensor on PSLV interface Board

Title PILOT Sensor interface Board Version3		
Size A4	Number	Revision
Date: 1-13-2023	Sheet of	
File: D:\Main\...\Connectors.SchDoc	Drawn By: Arosish Priyadarshan	