





# CONNECTORS TO XMC 4500 RELAX KIT




# STEP-UP CONVERTER 3.2V TO 5V




# SERIAL INTERFACE TO RASPBERRY PI



# RESET XMC



# INTERFERENCE ELIMINATION



# POWER SUPPLY ON/OFF BUTTON

