





CONNECTORS TO XMC 4500 RELAX KIT




STEP-UP CONVERTER 3.2V TO 5V




SERIAL INTERFACE TO RASPBERRY PI



RESET XMC



INTERFERENCE ELIMINATION



POWER SUPPLY ON/OFF BUTTON

