



Overview				Site
Inspect N	34781	Page:	1/1	<div>ROTHERHAM DO/OFF</div> <div>MAIN STREET</div> <div>ROTHERHAM</div> <div>S60 1AA</div>
Job No	12332			
Customer	AECOM			
Contact		Date	26/01/2024	
Tel				

### Pass

ISI Equipment No	Make / Model	Serial No	Client ID
RM090124389	Barrier Traffic		0000664346

#### Asset Photograph

Capture photograph of Asset, including asset number	See Photo 1
---	-------------

#### Hazard Priority and Findings

Intolerable - Defects requiring immediate action	None
Substantial - Defects requiring attention within a time period	None
Moderate - Other defects requiring attention	Multiple barrier fixings are loose and insecure these are to be rectified.
Tolerable - Observations	None



#### General Comments

We advise the equipment be maintained and lubricated in accordance with manufacturers recommendations and a maintenance log maintained for high risk equipment in accordance with Provision and Use of Work Equipment Regulations 1998 ( PUWER ) Regulation 5.

#### Engineer

Danny Earl