

IFAD MOTORS LTD

Head Office

DMS JC


2644

Ref.No:	Narsingdi- October-2020/49	F.R SI NO#	49	Date:	14.10.2020
Zone Name:	Narsingdi	Engineer/Sr.Mechanic Name:	Sujon Mia		
Approved by:	Prabir Biswas-Head of Service & Spare Parts.				
Customer Name:	BILLAL HOSSAIN		Mobile No:	01784-036470	
Address:	Etakhola,Narsingdi		Dealer Name:	S.M Enterprise	
Customer Complain:- Self Start Problem.	CH NO Full #	MD6M14CL1K4P00092			
	EN NO Full #	0L4PK4700402			
	Sale Date #	14.10.2020		Present Km	90
	Date of Comp#	14.10.2020		Model #	Tvs king Duramax CNG
	Date of Repair #				
	Free Cupon service information				
	1St Free Service		2nd Free Service		3rd Free Service
Date	KMS	Date	KMS	Date	KMS

Obserbation & Analysis:(By Engineer) We checked & found that Ignition Coil Short.

Action Taken:- Yet to be replace front Ignition Coil by new one under warranty.

Failure Particular						
SL	Part NO	Part Name	Qty	Vendor code	Approved	Rejected
1	G4060250	IGNITION COIL WITH SUP. CAP 4	1PC			
2						
3						
4						
5						
6						

Failure Parts Photo	For Head Office Use
	 14/10/2020

14/10/2020

Mitun Saheer  
14.10.2020  
DMS complete