

Paid



Receipt #28817

Billing Address

87108161
#0211, block B, the orient,
251 pasir panjang rd,
118610
foxxiuxiu@gmail.com
+65 8710 8161

Service Address

87108161
#0211, block B, the orient,
251 pasir panjang rd,
118610
foxxiuxiu@gmail.com
+65 8710 8161

Send Payment To

338 Aircon
15 Duku Road #01-01
Singapore 429165
Singapore 429165
+6592224141
hello@338aircon.sg

Invoice Date	05/08/23
Sent On	05/08/23
Paid On	05/08/23
Total	\$75.00
Payments	\$75.00
Balance	\$0.00

Charges

Item	Description	Unit Cost	Tax	Quantity	Line Total
Normal Servicing	Basic servicing of aircon 2 units	\$75.00	×	1.0	\$75.00
Subtotal					\$75.00
Tax					\$0.00
Total					\$75.00
Total payments					\$75.00
Balance remaining					\$0.00

Notes

Thank you for your business!

Terms

Payment terms:

For installation: 40% deposit, 60% upon completion
For servicing, chemical wash / overhaul, replacement of spoilt parts: 100% upon completion
For contract: 100% upfront upon signing of contract

Payment methods:

Paynow to: 202022932H
Cheque payable to: 338 PRIVATE LIMITED
Bank transfer to: 601262124001 (OCBC)

Warranty:

For general servicing warranty: 30 days warranty for aircon leaking
For contract servicing warranty: 30 days from the completion of last servicing date for aircon leaking
For recon repair warranty: 30 days from the repair date

For contract customers:

- It is the customer's responsibility to arrange for aircon servicing every 3 months. Outside of 3 months, company will not be liable for the warranty for gas top up, free site inspection and transport fee.
- It is the customer's responsibility to update 338 Aircon for any changes in customer address, phone number during the period of the contract.
- Unless stated above in the invoice item description, contract does not include gas top ups, pipe changes, chemical wash or overhaul, repairs, change of parts, replacement of units or installations.

- 338 PTE LTD bears no responsibility for any damage arising from the servicing of the aircon unit unless proven with before and after photos that the faulty part was damaged by our technician during the servicing.
- 338 PTE LTD bears no responsibility for any damages to any item or property arising from the rendering of service to customers. Any items in the house are under the responsibility of the customer - any damages to items not removed by customers that are placed near / under / around the aircon units in the process of servicing will be borne by the owner.
- Any outstanding contracts not completed within the 1 year calendar time frame is deemed expired and will be forfeited without refund.

For installation:
- 2 years workmanship warranty on gas pipe, kindly note ONLY applies on signing service contract with us

Signatures

Name	Signature	Reason	Requested	Signed	Document
87108161		Completion of job - acceptance of work done	<div>Live signature</div>	May 8 2023 11:04 am	Invoice