


J3/X3  
Pinout



J2  
Termination

1-2 ON  
2-3 OFF

1-2 Default

X1

