


Install TopWin6

For Windows XP (x86)

NOTE: Don't connect programmer during the installation

- 1.Run Setup.exe;
- 2.When inter Setup window, Select language 'Intl English',then click [OK];
- 3.Click [Next], Complete all the step;
- 4.Reset computer;
- 5.Connect TOP Programmer, System will find the driver and load it.The device show in Device Manager window as:




(WinDriver version is 10.2.1.0)

USB Troubleshooting

If the computer can't find the driver you can reload the driver as following:

1. Open 'Device Manager' window:
2. Find the device line with a '!',(it is an error) in Device Manager window:




3. Don't Select 'Auto...',You must load usb driver form [disk].You had to input the path:

For Top Programmer is C:\Top\Topwin6\driver\xp\ TopUSB3.inf;

For WinDriver is C:\Top\Topwin6\driver\xp\ windriver6.inf.

You had to update both two lines.

- 4.Reset computer;
- 5.Connect TOP Programmer, System will find the driver and load it.
6. The device show in Device Manager window as:



Driver software path C:\Top\Topwin6\driver\xp\

NOTE: Don't connect programmer when setup.