

Problem Definition. Write an 8051 Program to Transfer the block from internal memory location 30h to internal memory location 40h.