



The 74LS11 that generate dtack signal have input signals from other circuits.

Im not certain if the dtack signal pin in MC68681 is open collector.

By using the 74LS11, any other peripheral must have his dtack signal used as input for generate the final dtack signal.

I belive that the 74LS11 should be replaced by a an open collector output circuit.