






Title		
Size A4	Number	Revision
Date:	07/12/2020	Sheet of
File:	01 a splitFlapDetector.SchDoc	Drawn By:




Title		
Size	Number	Revision
A4		
Date:	07/12/2020	Sheet of
File:	01 b syncDetector.SchDoc	Drawn By:




Title		
Size A4	Number	Revision
Date: 07/12/2020	Sheet of	
File: 01 c stepperDriver.SchDoc	Drawn By:	




Title		
Size	Number	Revision
A4		
Date:	07/12/2020	Sheet of
File:	01_splitFlapClock.SchDoc	Drawn By:









Title		
Size	Number	Revision
A4		
Date:	07/12/2020	Sheet of
File:	02_radioTuner.SchDoc	Drawn By:




Title		
Size	Number	Revision
A4		
Date:	07/12/2020	Sheet of
File:	03_audioAmp.SchDoc	Drawn By:



Title		
Size	Number	Revision
A4		
Date:	07/12/2020	Sheet of
File:	04 light.SchDoc	Drawn By:



Title		
Size	Number	Revision
A4		
Date:	07/12/2020	Sheet of
File:	05_radioTransceiver.SchDoc	Drawn By:



Title		
Size A4	Number	Revision
Date:	07/12/2020	Sheet of
File:	06 airSensors.SchDoc	Drawn By: