



(02) 796 5092 📞  
rakkiiautoservices@yahoo.com 📧  
71 Santol St.Niño, Quezon City, 1113 📍

REPAIR JOB ESTIMATE			
Customer:	Janrey A. Cablinda	Date:	2021-12-12
Address:	San juan 2 lapasan CDO		
Insurance:	PHIL. BRITISH		
Vehicle:	VIOS	PLATE NO.:	KVN999
SCOPE OF WORK			
		LABOR	LABOR
I - PARTS TO BE REPAIR		₱0	₱0
FRT BUMBER COVER		₱1000	₱1000
II - PULLDOWN ALL NEC. PARTS TO GIVEWAY FOR REPAIR		₱0	₱0
test		₱200	₱200
SUB-TOTAL:		₱1200	₱1200
12% VAT:		₱144	
TOTAL LABOR AND PARTS		₱2544	FRED MORAN
The above ESTIMATE is based on our inspection and does not cover/include broken or additional labor which are not evident on the first inspection. Qoutation and parts/labor are current and subject to change notice. This estimate is only good for fifteen days, and is NOT VALID FOR COURT PURPOSES. RAKKII AUTO SERVICE shall not be liable for loss/es or any damage/s to vehicle or any		APPROVED BY REZZA LYNN BITENG	
		GENERAL MANAGER	