


Packaging Arrangement Guidance						Category: B-B					
Part Number:		Rev	06	Area	MOLDING	PARTS ARRANGEMENT REQUIREMENT					
Process		ILLUSTRATION									
INJ						P-CASE QUANTITY		PLASTIC QUANTITY			
						QUANTITY PARTS PER ROW:	N/A	SMALL (3x6):	N/A		
						TOTAL NO. OF ROW:	N/A	MEDIUM (6x8):	N/A		
						QUANTITY PER LAYER:	N/A	LARGE (10x14):	100		
						TOTAL NO. OF LAYER:	N/A	MAXIMUM PLASTIC PER P-CASE:	5		
						QUANTITY PER P-CASE	500			PAPER LINER: <input checked="" type="checkbox"/>	
						QUANTITY PER BUCKET:	N/A			CUSHION FOAM: <input type="checkbox"/>	
										CARTON: <input type="checkbox"/>	
										BUBBLE SHEET: <input type="checkbox"/>	
P-CASE :						BUCKET BOX :					
<input checked="" type="checkbox"/> BLUE	<input type="checkbox"/> LIGHT	<input type="checkbox"/> SMALL	<input type="checkbox"/> DARK	<input type="checkbox"/> GRAY	<input type="checkbox"/> WHITE	<input type="checkbox"/> SMALL	<input type="checkbox"/> BLUE	<input type="checkbox"/> SMALL	<input type="checkbox"/> YELLOW	<input type="checkbox"/> WHITE	
											
						Prepared by:	Reviewed by:	Approved by:	DATE		
									03/15/2018		
									PAGE		
01	04/29/2019	B.M. Rodriguez	Additional parts category.			B.M. Rodriguez	F. Mediente	S. Lorete	1/1		
REV.NO	REV.DATE	REVISED BY	DESCRIPTION								