


Pin 1



IN+ (RED)

OUT- (WHITE)

Compensation Resistor

Pin 1

OUT+ (GREEN)

Solder

IN- (BLACK)

