



HEAT and GND traces between the Base unit connector and Tip connector need to be able to carry 5A so trace needs to be a minimum of 4mm