



HEAT and GND traces between the Base unit connector and Tip connector need to be able to carry 5A so trace needs to be a minimum of 4mm

Hotstick Wand		
Sheet: /		
File: Wand.sch		
Title:		
Size: A4	Date:	Rev:
KiCad E.D.A. kicad 4.0.1-stable		Id: 1/1