









Caps should be placed as close to power pins as possible
Use ceramic caps



Output Resistors - As close to Output TPA pin as possible

Input and Feedback Resistors -- As close to TPA input pin as possible



Resistor dividers for R/L IN+