
















Power Supply



danjuliodesigns, LLC	
TITLE: miif	
Document Number:	REV: 2
Date: 4/11/24 8:00 PM	Sheet: 1/7

Raspberry Pi 4 Compute Module





danjuliodesigns, LLC

TITLE: miif



Document Number: REV: 2

Date: 4/11/24 8:00 PM Sheet: 2/7









Ethernet Hub Configuration



Default LED Mode 0



802.1p disabled by default



Hardware configuration for non-default values
(see KS8997 User Manual for details)

danjuliodesigns, LLC





TITLE: miif

Document Number:


REV:
2

Date: 4/11/24 8:00 PM

Sheet: 5/7



100 ohm differential routing



danjuliodesigns, LLC




TITLE: miif

Document Number:



REV:
2

Date: 4/11/24 8:00 PM

Sheet: 6/7



100 ohm differential routing



danjuliodesigns, LLC

TITLE: miif

Document Number:

REV:
2

Date: 4/11/24 8:00 PM

Sheet: 7/7