


CYBORG EYE PATCH

1

Use pen to outline mask on EVA foam with template. Cut out EVA foam mask with hot knife (or laser cutter).




Materials:
1/2" or 3/8" thick EVA foam
Contact Cement or Glue Gun
Mod Podge
Wire

Tools:
Hot Knife (laser cutter?)
Heat Gun
Glue Gun
Brushes
Sand Paper


2

Use heat gun to heat and contour eye patch.




3

Use contact cement or gluegun to close darts. Hold until dried. Smooth out seam with silicone filler.




4

Use contact cement or glue gun to attach gear or gear alternative centered on eye patch.




6

Smooth with brushed layer of Mod Podge, sanding when dry. Repeat if smooth finish is desired. Make holes, and glue gun in wires. Metallic paint for finishing touch.



5

Use glue gun to attach elastic strap.



7

Glue gun 3D printed dome into center of gear with coin battery and LED underneath.