



ADJUSTABLE DC-DC CONVERTER


Ensure capacitors have appropriate voltage ratings
When output relay is switched off, maybe it is a good idea to shutdown this converter first




CURRENT MEASUREMENT




LINEAR PSU




OUTPUT RELAY




5V LDO




12V LDO




3.3V LDO



2.048V VREF



PWM-DAC FILTERS



CURRENT SOURCE

