

## Defect Record Sheet

<b>A</b>	Defect Ref No : <u>SW2-MAS3-EXT-WK004-047</u>		Date / Time : <u>16/9/2022</u>	
	Repeated defect: (Yes/ No) <u>Yes</u>			
	Type of Road /Footpath/Facilities : <u>Major</u>			
	Location / Landmark:	<u>Tuas Checkpoint</u>	<u>LP 25F</u>	
	Type of Asset:	<u>Railing</u>		
	Description:	<u>Railing-Damaged</u>		
	Quantity:	<u>4 Members</u>		
	Measurement:	<u>4 Members</u>		
	Cause of Defect:	<u>Hit By Vehicle</u>		
	Recommendation:	<u>To Replace</u>		
	Inspected By :	<u>John</u>		
		<u>Name</u>	<u>Signature</u>	
	Supervised By :	<u>Joe Mama</u>		
		<u>Name</u>	<u>Signature</u>	
<b>Defects reported to DRC / RARL / RIA / other agencies on:</b>				
Reported via:	Method / Agency / Date / Time:	<u>DRC</u>		
Acknowledgement:	Method / Date / Time:	<u>Looking method</u>		
<b>B</b>	(For LTA Use)			
	Defects Verified by :	<u>Steve Jobs</u>	<u>01/01/1984</u>	
		<u>Name</u>	<u>Signature</u>	<u>Date</u>
	Instructions:	<u>Instructions stuff</u>		
<b>C</b>	(For contractor's acknowledgement)			
	Acknowledged and received by:	<u>Thomas Ng</u>	<u>02/04/2000</u>	
		<u>Name</u>	<u>Signature</u>	<u>Date</u>
TR322				