


## A

B

c

D



R30 is to allow more creepage when used with 240V. It's 0R for 120V

[illegible]

Possibly use a smaller inductor for L2?  
It still has high pulsed currents at startup

Possibly find another regulator that can handle cheaper output caps?