

**MOTOMARK**

Hybrid & New Vehicle Repair Center

No.255/1/A, Kahanthota Road, Malabe.

Tel : +94 11 7 831 199

Mobile: +94 76 1 966 183

+94 71 5 648 799

E-Mail : indikaprab@gmail.com

Date: 04/05/2022

INVOICE

IN NO: 170

Name: South asia apparel

Address: PT-3547

Item	Description	Unit Price	Quantity	Amount
01)	DPT Remove and Re programmed catalyst System.		01	28,000.00
02)	Silencer welding and all service charge.			6000.00
TOTAL				34000.00

Authorized signature

Customer signature



Brand New Spare parts Supplier / Vehicle Repair



No.255/1/A, Kahanthota Road, Malabe.
Tel : +94 11 7 831 199
Mobile: +94 76 1 966 183
+94 71 5 648 799
E-Mail : indikaprab@gmail.com

IN NO: 164

Item	Description	Unit Price	Quantity	Amount
	Tonyada KDH linen	26500/-	01	26500/-
	SRT			2700/-
	Rear Linen replacement			
	Paste the disk's front	19000/-	02	38000/-
	Disk Repitting and Clean Printed B. Pells		01	3400/-
TOTAL				36,400/-

TOTAL

Customer signature

Authorized signature



Brand New Sports parts Supplier / Vehicle Repair