




USB




Auto Reset




PWR IN & PWR MANAGEMENT




MCU




Expansion




LED




Antenna




Stepper



Symbols



Mounting_holes



Sheet: /
File: stepper_driver.sch

Title:

Size: A3

Date:

KiCad E.D.A. kicad (5.1.9)-1

Rev:

Id: 1/1