

## Verification Report

Generated by MIG Version 3.6.1 on Tue Nov 24 08:02:23 2015

Reading design libraries of xc3s700an-fgg484... successful !

```
/*  
/*          Controller 0  
/*  
ERROR: The signal VGA_B[3] is allocated to an invalid IO.  
ERROR: All the dqs signal(s)/pin(s) are missing.
```