










	Model	Model No.	Description	Price
		SSC-NMA	<b>Handle:</b> Adjustable with PU pad <b>Machine:</b> Tilt <b>Base:</b> Metal spider <b>Castor :</b> Nylon <b>Type:</b> Matrix	6400
		SSC-NMN	<b>Handle:</b> Nylon <b>Machine:</b> Tilt <b>Base:</b> Metal spider <b>Castor :</b> Nylon <b>Type:</b> Matrix	6100
		SSC-NBH	<b>Handle:</b> Nylon <b>Machine:</b> Tilt <b>Base:</b> Metal spider <b>Castor :</b> Nylon <b>Type:</b> Bravo HB	4600
		SSC-NBM	<b>Handle:</b> Nylon <b>Machine:</b> Tilt <b>Base:</b> Metal spider <b>Castor :</b> Nylon <b>Type:</b> Bravo MB	4200
		SSC-NBO	<b>Handle:</b> Nylon <b>Machine:</b> Tilt <b>Base:</b> Metal spider <b>Castor :</b> Nylon <b>Type:</b> Boom	4000


		SSC-N898	<b>Handle:</b> Nylon <b>Machine:</b> Tilt <b>Base:</b> Metal spider <b>Castor :</b> Nylon <b>Type:</b> 898	3900
		SSC-NIF	<b>Handle:</b> Nylon <b>Machine:</b> Tilt <b>Base:</b> Metal spider <b>Castor :</b> Nylon <b>Type:</b> Net Iron Frame	4500
		SSC-NMO	<b>Handle:</b> Nylon <b>Machine:</b> Tilt <b>Base:</b> Metal spider <b>Castor :</b> Nylon <b>Type:</b> Mono	4600
		SSC –SP01	<b>Handle:</b> Chrome PP <b>Machine:</b> Push Bac <b>Base:</b> Metal spider <b>Castor :</b> Nylon <b>Type:</b> Synchro PB	5200



		SSC –SP02	<b>Handle:</b> Chrome PP <b>Machine:</b> Push Bac <b>Base:</b> Metal spider <b>Castor :</b> Nylon <b>Type:</b> Synchro PB	5200
		SSC –SP03	<b>Handle:</b> Chrome PP <b>Machine:</b> Push Bac <b>Base:</b> Metal spider <b>Castor :</b> Nylon <b>Type:</b> Synchro PB	5200
		SSC –CP01	<b>Handle:</b> SS Cush <b>Machine:</b> Push Bac <b>Base:</b> Metal spider <b>Castor :</b> Nylon <b>Type:</b> Comp PB	4900
		SSC –J601	<b>Handle:</b> 603 <b>Machine:</b> Tilt <b>Base:</b> Metal spider <b>Castor :</b> Nylon <b>Type:</b> Jod Ply	6400

		SSC – J602	<b>Handle:</b> 603 <b>Machine:</b> Tilt <b>Base:</b> Metal spider <b>Castor :</b> Nylon <b>Type:</b> Jod Ply	6400
		SSC – J603	<b>Handle:</b> 603 <b>Machine:</b> Tilt <b>Base:</b> Metal spider <b>Castor :</b> Nylon <b>Type:</b> Jod Ply	6400
		SSC – J604	<b>Handle:</b> 603 <b>Machine:</b> Tilt <b>Base:</b> Metal spider <b>Castor :</b> Nylon <b>Type:</b> Jod Ply	6400
		SSC – J605	<b>Handle:</b> 603 <b>Machine:</b> Tilt <b>Base:</b> Metal spider <b>Castor :</b> Nylon <b>Type:</b> Jod Ply	6400
		SSC – J606	<b>Handle:</b> 603 <b>Machine:</b> Tilt <b>Base:</b> Metal spider <b>Castor :</b> Nylon <b>Type:</b> Jod Ply	6400

		SSC – J607	<b>Handle:</b> 603 <b>Machine:</b> Tilt <b>Base:</b> Metal spider <b>Castor :</b> Nylon <b>Type:</b> Jod Ply	6400
		SSC – J608	<b>Handle:</b> 603 <b>Machine:</b> Tilt <b>Base:</b> Nylon Coating <b>Castor :</b> Nylon <b>Type:</b> Jod Ply	6800
		SSC – J609	<b>Handle:</b> 603 <b>Machine:</b> Tilt <b>Base:</b> Nylon Coating <b>Castor :</b> Nylon <b>Type:</b> Jod Ply	6800
		SSC – J610	<b>Handle:</b> 603 <b>Machine:</b> Tilt <b>Base:</b> Nylon Coating <b>Castor :</b> Nylon <b>Type:</b> Jod Ply	6800
		SSC – J611	<b>Handle:</b> 603 <b>Machine:</b> Tilt <b>Base:</b> Nylon Coating <b>Castor :</b> Nylon <b>Type:</b> Jod Ply	6800

		SSC – J612	<b>Handle:</b> 603 <b>Machine:</b> Tilt <b>Base:</b> Nylon Coating <b>Castor :</b> Nylon <b>Type:</b> Jod Ply	6800
		SSC – J613	<b>Handle:</b> 603 <b>Machine:</b> Tilt <b>Base:</b> Metal spider <b>Castor :</b> Nylon <b>Type:</b> Jod Ply	7000
		SSC – JS14	<b>Handle:</b> SS <b>Machine:</b> Tilt <b>Base:</b> Metal spider <b>Castor :</b> Nylon <b>Type:</b> Jod Ply	6600
		SSC – JS15	<b>Handle:</b> SS <b>Machine:</b> Tilt <b>Base:</b> Metal spider <b>Castor :</b> Nylon <b>Type:</b> Jod Ply	7000
		SSC – JS16	<b>Handle:</b> SS <b>Machine:</b> Tilt <b>Base:</b> Metal spider <b>Castor :</b> Nylon <b>Type:</b> Jod Ply	7000

		SSC – JF17	<b>Handle:</b> Folding <b>Machine:</b> Tilt <b>Base:</b> Metal spider <b>Castor :</b> Nylon <b>Type:</b> Jod Ply	6700
		SSC – JF18	<b>Handle:</b> Folding <b>Machine:</b> Tilt <b>Base:</b> Metal spider <b>Castor :</b> Nylon <b>Type:</b> Jod Ply	6700
		SSC – JF19	<b>Handle:</b> Folding <b>Machine:</b> Tilt <b>Base:</b> Metal spider <b>Castor :</b> Nylon <b>Type:</b> Jod Ply	7200
		SSC – JR19	<b>Handle:</b> 633 <b>Machine:</b> Tilt <b>Base:</b> Nylon Coating <b>Castor :</b> Nylon <b>Type:</b> Jod Ply	7000
		SSC – J821	<b>Handle:</b> 821 <b>Machine:</b> Tilt <b>Base:</b> Metal spider <b>Castor :</b> Nylon <b>Type:</b> Jod Ply	6700

		SSC – J822	<b>Handle:</b> 817 <b>Machine:</b> Tilt <b>Base:</b> Metal spider <b>Castor :</b> Nylon <b>Type:</b> Jod Ply	6500
		SSC – J823	<b>Handle:</b> 817 <b>Machine:</b> Tilt <b>Base:</b> Bolish <b>Castor :</b> Nylon <b>Type:</b> Jod Ply	6900
		SSC – J824	<b>Handle:</b> 817 <b>Machine:</b> Tilt <b>Base:</b> Metal spider <b>Castor :</b> Nylon <b>Type:</b> Jod Ply	6500



		SSC – J825	<b>Handle:</b> 817 <b>Machine:</b> Tilt <b>Base:</b> Metal spider <b>Castor :</b> Nylon <b>Type:</b> Jod Ply	6500
		SSC - J826	<b>Handle:</b> 817 <b>Machine:</b> Tilt <b>Base:</b> Metal spider <b>Castor :</b> Nylon <b>Type:</b> Jod Ply	6500
		SSC – J827	<b>Handle:</b> 817 <b>Machine:</b> Tilt <b>Base:</b> Metal spider <b>Castor :</b> Nylon <b>Type:</b> Jod Ply	6500
		SSC - J828	<b>Handle:</b> 817 <b>Machine:</b> Tilt <b>Base:</b> Metal spider <b>Castor :</b> Nylon <b>Type:</b> Jod Ply	6600
		SSC - J829	<b>Handle:</b> Utype <b>Machine:</b> Tilt <b>Base:</b> Nylon <b>Castor :</b> Nylon <b>Type:</b> Jod Ply	6000

		SSC - J830	<b>Handle:</b> Utype <b>Machine:</b> Tilt <b>Base:</b> Nylon <b>Castor :</b> Nylon <b>Type:</b> Jod Ply	6500
		SSC – J831	<b>Handle:</b> 817 <b>Machine:</b> Tilt <b>Base:</b> Metal spider <b>Castor :</b> Nylon <b>Type:</b> Jod Ply	6700
		SSC – J832	<b>Handle:</b> 817 <b>Machine:</b> Tilt <b>Base:</b> Metal spider <b>Castor :</b> Nylon <b>Type:</b> Jod Ply	6700

		SSC – LS01	<b>Handle:</b> Steel <b>Machine:</b> Torsion <b>Base:</b> Metal (Air) <b>Castor :</b> Alloy <b>Type :</b> Lply	10400
		SSC – LS01S	<b>Handle:</b> Steel <b>Machine:</b> Torsion <b>Base:</b> Metal (Air) <b>Castor :</b> Alloy <b>Type :</b> Lply	11000

		SSC – LS02	<b>Handle:</b> Steel <b>Machine:</b> Torsion <b>Base:</b> Metal (Air) <b>Castor :</b> Alloy <b>Type :</b> Lply	10400
		SSC – LS03	<b>Handle:</b> Steel <b>Machine:</b> Torsion <b>Base:</b> Metal (flair) <b>Castor :</b> Alloy <b>Type :</b> Lply	10600
		SSC – L804	<b>Handle:</b> 821 <b>Machine:</b> Torsion <b>Base:</b> Metal (Air) <b>Castor :</b> Alloy <b>Type :</b> Lply	11000
		SSC–LP05	<b>Handle:</b> Steel Sleek <b>Machine:</b> Torsion <b>Base:</b> Metal (Air) <b>Castor :</b> Alloy <b>Type :</b> Lply	10800
		SSC – LS06	<b>Handle:</b> Steel <b>Machine:</b> Torsion <b>Base:</b> Metal (Air) <b>Castor :</b> Alloy <b>Type :</b> Lply	10400

		SSC – LS07	<b>Handle:</b> Steel <b>Machine:</b> Torsion <b>Base:</b> Metal (Air) <b>Castor :</b> Alloy <b>Type :</b> Lply	10000
		SSC – LL08	<b>Handle:</b> Ltype Nylon <b>Machine:</b> Torsion <b>Base:</b> Nylon (Coated) <b>Castor :</b> Alloy <b>Type :</b> Lply	10000
		SSC – L809	<b>Handle:</b> 817 <b>Machine:</b> Torsion <b>Base:</b> Metal (Air) <b>Castor :</b> Alloy <b>Type :</b> Lply	10200
		SSC – LP10	<b>Handle:</b> Steel <b>Machine:</b> Torsion <b>Base:</b> Metal (Flair) <b>Castor :</b> Alloy <b>Type :</b> Lply	11000
		SSC – LP11	<b>Handle:</b> Steel <b>Machine:</b> Torsion <b>Base:</b> Metal (Flair) <b>Castor :</b> Alloy <b>Type :</b> Lply	11000

		SSC – LP12	<b>Handle:</b> Steel <b>Machine:</b> Torsion <b>Base:</b> Metal (Flair) <b>Castor :</b> Alloy <b>Type :</b> Lply	11000
		SSC – L613	<b>Handle:</b> 633 <b>Machine:</b> Torsion <b>Base:</b> Nylon Coat <b>Castor :</b> Alloy <b>Type :</b> Lply	10000
		SSC – L814	<b>Handle:</b> 817 <b>Machine:</b> Torsion <b>Base:</b> Bolish <b>Castor :</b> Alloy <b>Type :</b> Lply	10000
		SSC – L815	<b>Handle:</b> 817 <b>Machine:</b> Torsion <b>Base:</b> Bolish <b>Castor :</b> Alloy <b>Type :</b> Lply	10000
		SSC – LS16	<b>Handle:</b> SS <b>Machine:</b> Torsion <b>Base:</b> Metal (Flair) <b>Castor :</b> Alloy <b>Type :</b> Lply	10400

		SSC – LP17	<b>Handle:</b> Steel <b>Machine:</b> Torsion <b>Base:</b> Metal (Flair) <b>Castor :</b> Alloy <b>Type :</b> Lply	11000
		SSC – LS18	<b>Handle:</b> Steel <b>Machine:</b> Torsion <b>Base:</b> Metal (Flair) <b>Castor :</b> Alloy <b>Type :</b> Lply	10400
		SSC – LS19	<b>Handle:</b> Steel <b>Machine:</b> Torsion <b>Base:</b> Metal (Air) <b>Castor :</b> Alloy <b>Type :</b> Lply	10400
		SSC – LS20	<b>Handle:</b> Steel <b>Machine:</b> Anytime <b>Base:</b> Metal (Flair) <b>Castor :</b> Alloy <b>Type :</b> Lply	9400
		SSC – LS21	<b>Handle:</b> Steel <b>Machine:</b> Torsion <b>Base:</b> Metal (Air) <b>Castor :</b> Alloy <b>Type :</b> Lply	10400

		SSC – LS22	<b>Handle:</b> Steel <b>Machine:</b> Torsion <b>Base:</b> Metal (Air) <b>Castor :</b> Alloy <b>Type :</b> Lply	10400
		SSC – LS23	<b>Handle:</b> Steel <b>Machine:</b> Anytime <b>Base:</b> Metal (Flair) <b>Castor :</b> Alloy <b>Type :</b> Lply	9400
		SSC – RC01	<b>Handle:</b> Wood <b>Machine:</b> Torsion <b>Base:</b> Metal (Flair) <b>Castor :</b> Alloy <b>Type :</b> Recliner	17500
		SSC – RS02	<b>Handle:</b> Wood <b>Machine:</b> Torsion <b>Base:</b> Wooden <b>Castor :</b> Alloy <b>Type :</b> Recliner	17500




		SSC – RSE03	<b>Handle:</b> 821 <b>Machine:</b> Torsion <b>Base:</b> Flair <b>Castor :</b> Alloy <b>Type :</b> Semi Recliner	12000
		SSC – RSE04	<b>Handle:</b> 821 <b>Machine:</b> Torsion <b>Base:</b> Flair <b>Castor :</b> Alloy <b>Type :</b> Semi Recliner	12000
		SSC – SC01	<b>Handle:</b> <b>Machine:</b> Torsion <b>Base:</b> Flair <b>Castor :</b> Alloy <b>Type :</b> Sofa	12000
		SSC – SC02	<b>Handle:</b> <b>Machine:</b> Torsion <b>Base:</b> Flair <b>Castor :</b> Alloy <b>Type :</b> Sofa	13000





		SSC – SC03	<b>Handle:</b> <b>Machine:</b> Torsion <b>Base:</b> Flair <b>Castor :</b> Alloy <b>Type :</b> Sofa	13000
		SSC – SC04	<b>Handle:</b> <b>Machine:</b> Torsion <b>Base:</b> Flair <b>Castor :</b> Alloy <b>Type :</b> Sofa	13000
		SSC – SC05	<b>Handle:</b> <b>Machine:</b> Torsion <b>Base:</b> Flair <b>Castor :</b> Alloy <b>Type :</b> Sofa	12500
		SSC – FW01	<b>Handle:</b> Wood <b>Machine:</b> Torsion <b>Base:</b> Flair <b>Castor :</b> Alloy <b>Type :</b> Frame	13000

		SSC – FS02	<b>Handle:</b> SS <b>Machine:</b> Torsion <b>Base:</b> Flair <b>Castor :</b> Alloy <b>Type :</b> Frame	11500
--	--	------------	--	-------

		SSC – FS03	<b>Handle:</b> SS <b>Machine:</b> Torsion <b>Base:</b> Flair <b>Castor :</b> Alloy <b>Type :</b> Frame	11500
		SSC – FP04	<b>Handle:</b> Ltype <b>Machine:</b> Torsion <b>Base:</b> Metal(Spider) <b>Castor :</b> Nylon <b>Type :</b> Frame	8000
		SSC – CLP01	<b>Handle:</b> 817 <b>Machine:</b> Tilt <b>Base:</b> Metal spider <b>Castor :</b> Nylon <b>Type:</b> MB L Ply	5400
		SSC – CLP02	<b>Handle:</b> 603 <b>Machine:</b> Tilt <b>Base:</b> Metal spider <b>Castor :</b> Nylon <b>Type:</b> MB L Ply	5200





		SSC – CLP03	<b>Handle:</b> U type <b>Machine:</b> Tilt <b>Base:</b> Metal spider <b>Castor :</b> Nylon <b>Type:</b> MB L Ply	5000
		SSC – CLP04	<b>Handle:</b> U type <b>Machine:</b> Tilt <b>Base:</b> Bolish <b>Castor :</b> Nylon <b>Type:</b> MB L Ply	5000
		SSC – CLP05	<b>Handle:</b> U type <b>Machine:</b> Tilt <b>Base:</b> Bolish <b>Castor :</b> Nylon <b>Type:</b> MB L Ply	5000
		SSC – CLP06	<b>Handle:</b> 817 <b>Machine:</b> Tilt <b>Base:</b> Metal spider <b>Castor :</b> Nylon <b>Type:</b> MB L Ply	5300
		SSC – CLP07	<b>Handle:</b> 603 <b>Machine:</b> Tilt <b>Base:</b> Metal spider <b>Castor :</b> Nylon <b>Type:</b> MB L Ply	5400

		SSC – CLP08	<b>Handle:</b> 817 <b>Machine:</b> Tilt <b>Base:</b> Metal spider <b>Castor :</b> Nylon <b>Type:</b> MB L Ply	5500
		SSC – CLP09	<b>Handle:</b> U type <b>Machine:</b> Tilt <b>Base:</b> Metal spider <b>Castor :</b> Nylon <b>Type:</b> MB L Ply	5200
		SSC – CLP10	<b>Handle:</b> 817 <b>Machine:</b> Tilt <b>Base:</b> Metal spider <b>Castor :</b> Nylon <b>Type:</b> MB L Ply	5500
		SSC – CLP11	<b>Handle:</b> Folding <b>Machine:</b> Tilt <b>Base:</b> Bolish <b>Castor :</b> Nylon <b>Type:</b> MB L Ply	5600
		SSC – CLP12	<b>Handle:</b> 817 <b>Machine:</b> Tilt <b>Base:</b> Metal spider <b>Castor :</b> Nylon <b>Type:</b> MB L Ply	5400






	SSC – CLP13	<b>Handle:</b> U type <b>Machine:</b> Tilt <b>Base:</b> Metal spider <b>Castor :</b> Nylon <b>Type:</b> MB L Ply	5000
	SSC – CLP14	<b>Handle:</b> Folding <b>Machine:</b> Tilt <b>Base:</b> Bolish <b>Castor :</b> Nylon <b>Type:</b> MB L Ply	5600
	SSC – CLP15	<b>Handle:</b> U type <b>Machine:</b> Tilt <b>Base:</b> Metal spider <b>Castor :</b> Nylon <b>Type:</b> MB L Ply	5400
	SSC – CLP16	<b>Handle:</b> SS <b>Machine:</b> Tilt <b>Base:</b> Metal Spider <b>Castor :</b> Nylon <b>Type:</b> MB L Ply	6000
	SSC – CLP17	<b>Handle:</b> U type <b>Machine:</b> Tilt <b>Base:</b> Bolish <b>Castor :</b> Nylon <b>Type:</b> MB L Ply	4800





		SSC – G01	<b>Handle:</b> <b>Machine:</b> Tilt <b>Base:</b> Bolish <b>Castor :</b> Nylon <b>Type:</b> Godrej	3800
		SSC – G02	<b>Handle:</b> <b>Machine:</b> Tilt <b>Base:</b> Bolish <b>Castor :</b> Nylon <b>Type:</b> Godrej	4200
		SSC – G03	<b>Handle:</b> <b>Machine:</b> Tilt <b>Base:</b> Bolish <b>Castor :</b> Nylon <b>Type:</b> Godrej	4000
		SSC – G04	<b>Handle:</b> <b>Machine:</b> Tilt <b>Base:</b> Bolish <b>Castor :</b> Nylon <b>Type:</b> Godrej	4000
		SSC – G05	<b>Handle:</b> <b>Machine:</b> Tilt <b>Base:</b> Bolish <b>Castor :</b> Nylon <b>Type:</b> Godrej	3600



		SSC – G06	<b>Handle:</b> <b>Machine:</b> Tilt <b>Base:</b> Bolish <b>Castor :</b> Nylon <b>Type:</b> Godrej	5600
		SSC – G07	<b>Handle:</b> <b>Machine:</b> Tilt <b>Base:</b> Bolish <b>Castor :</b> Nylon <b>Type:</b> Godrej	5600
		SSC – VF01	<b>Handle:</b> <b>Base:</b> SS Frame 1.25 inch <b>Type:</b> Godrej Visitor	5200
		SSC – VF02	<b>Handle:</b> <b>Base:</b> SS Frame 1.25 inch <b>Type:</b> Godrej Visitor	5200

		SSC - VF03	<b>Handle:</b> U type <b>Base:</b> SS Frame 1.25 inch <b>Type:</b> MB Jod Ply Visitor	5200
		SSC - VF04	<b>Handle:</b> 817 <b>Base:</b> SS Frame 1.25 inch <b>Type:</b> MB Jod Ply Visitor	6200
		SSC - VF05	<b>Handle:</b> 817 <b>Base:</b> SS Frame 1.25 inch <b>Type:</b> MB Jod Ply Visitor	6200
		SSC - VF06	<b>Handle:</b> U type <b>Base:</b> SS Frame 1.25 inch <b>Type:</b> MB Jod Ply Visitor	5000


		SSC - VF07	<b>Handle:</b> Nylon <b>Base:</b> SS Frame 1.25 inch <b>Type:</b> Net 898 Visitor	4000
		SSC - VF08	<b>Handle:</b> Nylon <b>Base:</b> SS Frame 1.25 inch <b>Type:</b> Net 898 Visitor	4000
		SSC - VF09	<b>Handle:</b> Nylon <b>Base:</b> Iron frame <b>Type:</b> Net Visitor	3200
		SSC – VF10	<b>Handle:</b> <b>Base:</b> SS <b>Type:</b> Visitor	3600
		SSC – VF11	<b>Handle:</b> <b>Base:</b> SS <b>Type:</b> Visitor	3700

		SSC – VF12	<b>Handle:</b> <b>Base:</b> SS <b>Type:</b> Visitor	5500
		SSC – VF13	<b>Handle:</b> <b>Base:</b> SS 1.25 inch <b>Type:</b> Visitor	4700
		SSC – VF13F	<b>Handle:</b> <b>Base:</b> SS 1.25 inch <b>Type:</b> Visitor	4500
		SSC – VF14	<b>Base:</b> SS <b>Type:</b> Visitor	3600
		SSC – VF15	<b>Base:</b> SS <b>Type:</b> Visitor	4000

		SSC – BS01	<b>Type:</b> Bar Stool	3800
		SSC - BS02	<b>Type:</b> Bar Stool	4400

		SSC - BS03	<b>Type:</b> Bar Stool	4200
		SSC - BS04	<b>Type:</b> Bar Stool	4400
		SSC - BS05	<b>Type:</b> Bar Stool	3800
		SSC - BS06	<b>Type:</b> Bar Stool	4000
		SSC - BS07	<b>Type:</b> Bar Stool	4000

		SSC - BS08	<b>Type:</b> Bar Stool	3400
		SSC- BS09	<b>Type:</b> Bar Stool	3000
		SSC – SC01	<b>Type:</b> SS Visitor Chair	2000
		SSC - SC02	<b>Type:</b> SS Visitor Chair	2200
		SSC - SC03	<b>Type:</b> SS Visitor Chair	2600

		SSC - SC04	<b>Type:</b> Metal Frame Chair	2300
--	--	------------	-----------------------------------	------