

Rows

Add Row

Delete

Charge Count

5

Apply

Files

Open CSV...

Save CSV...

Compute

Range

-5

to

5

Algorithm

FFT Powering

Compute Distribution

	Site	Copies	-2	-1	0	1	2	Sum
1		4		0.241716	0.439981	0.283518		
2		1	0.02602	0.251951	0.436698	0.263197		
3			0.011624	0.288577	0.427617	0.23798		
4		3	0.016217	0.223587	0.603753	0.140039		
5		1	0.017958	0.20211	0.45994	0.252993		
6		4	0.052975	0.264529	0.44522	0.217088		
7		1	0.029026	0.260493	0.416906	0.289866		
8		2		0.356616	0.290905	0.238056		


Missing fields detected:

Row 1: Charge '-2'

Row 3: Copies

Row 8: Charge '-2'

OK



Rows

Add Row

Delete

Charge Count

5

Apply

Files

Open CSV...

Save CSV...

Compute

Range

-2

to


2

Algorithm

FFT Powering

Compute Distribution

	Site	Copies	-2	-1	0	1	2	Sum
1		4	0.013775	0.241716	0.439981	0.283518		
2		1	0.02602	0.251951	0.436698	0.263197		
3		2	0.011624	0.288577	0.427617	0.23798		
4		3	0.016217	0.223587	0.603753	0.140039		
5		1	0.017958	0.20211	0.45994	0.252993		
6		4	0.052975	0.264529	0.44522	0.217088		
7		1	0.029026	0.260493	0.416906	0.289866		
8		2	0.044717	0.356616	0.290905	0.238056	0.069706	1.000000



Charge sum not exactly 1:
Row 1: sum=1.000001

OK

