


Use digital model for QRE sensor, less prone to noise and faster conversion than with ADC (analog)
From Polulu forum, digital performs better



Change Log:
2024/02/18 - Changed crystal to ceramic resonator and changed D1 to shottky diode
2024/04/05 - Changed 220 ohm res. and U3 capacitor for available stock
2024/04/20 - Changed U10 input 3&4 to A2 & A3