



* note: power gating the output of this LDO instead of vbat, to protect the MCU from overvoltage. wastes a little quiescent :(



ugh how to measure button state when it's also used for power on >_< TODO



BATTERY CHARGING

Sheet: /		D
File: blinky-puck.sch		
Title:		
Size: A4	Date:	Rev:
KiCad E.D.A. kicad 5.1.8—db983349188ubuntu20.10.1		Id: 1/1