




ARM7




SD




Dual Supply




Detect Power Loss



3.3V LDO




LiPo Charge




Options:
-With LiPo + charger: no R8
-Withtout LiPo: Mount R8 only

SD-Logger v1
by Christophe
(March 2012)
based on TWOG


Autopilot UART




Prog




Button




USB




Remote USB



SPI



I2C



Title		
Size	Number	Revision
A3		
Date:	30-3-2012	Sheet of
File:	C:\Documents and Settings\...\sdlogger.Sch	Drawn By: