


NOTES:

- MISSING:
- Range for Tone detector 67 - 254Hz (Resistor range verify - test)
 - 7805 Capacitors check
 - CHECK 330p pads at 5mm Caps (C10 done)
 - DC IN - Molex 3pin (Check cable)
 - Relay pads should be larger
 - C3 has polarity as tantalum... maybe polyester? pad size



Bottom (CTCSS, Carrier Delay Time and Time Out Timer)

Adapted from
CT4QC original

CT1ENQ, CT1EYN

Sheet: /

File: RepeaterController.sch

Title: Repeater Controller for NEUTEC 1630

Size: A4 Date: 2021-03-17

KiCad E.D.A. kicad 5.1.9-1.fc33

Rev: 1.0

Id: 1/1