

Note: Some K-Offset sensor require 5V or more.

Bias resistor for flow sensor

VS = 35V, R1 = ~ 5.6k

VS = 12V, R1 = ~ 2k

VS = 5V, R17 = ~ 1k

VS = 3.3V, R17 = ~ 1k

