







	Active		Metal1		N Well
	P+ Implant		Poly		Contact
	Metal2		N+ Implant		Via

Major tick=10 Minor tick=1 (UM)

