


TTV SUPPLYCHAIN CO., LTD. (TTV)
336/11 Moo 7 BoWin, Sriracha, Chonburi 20230
Tel: 033 -135 020



Work Order (WOD)

Order No (OC) : HMT-20240801002

Order Date : 02-Aug-24

Delivery Date : 05-Aug-24

Part No. : FA8E93 T0.5X295XCOIL

Work Order No. : WOD240801002

Document No. : PAC240804001

Document Date : 04-Aug-24

Creator : System


Created At : 04-08-2024 / 07:27:12

Item	Part No.	Part Description	FG Tag No	Total Net Weight (kg.)	Total Qty (PCS)	Case Tag No	Location	Weight/PCS (kg.)	Qty (PCS)	Net Weight (kg.)
1	FA8E93 T0.5X295XCOIL	AL T0.5x295xC(PLATE TUBE/SIDE)	F20240804004	921	2	R20240730119	HMT-RC01	460.5	1	460.5

Note :
F20240804004 : R20240730119-1

Checker
TTV SUPPLYCHAIN CO., LTD. (TTV)

TTV SUPPLYCHAIN CO., LTD. (TTV)
336/11 Moo 7 BoWin, Sriracha, Chonburi 20230
Tel: 033 -135 020



Work Order (WOD)

Order No (OC) :

HMT-20240801002

Order Date :

02-Aug-24

Delivery Date :

05-Aug-24

Part No. :

FA6690/7858/7859-O

Work Order No. :

WOD240801003

Document No. :

PAC240804001

Document Date :

04-Aug-24

Creator :

System

Created At :

04-08-2024 / 07:27:12

Item	Part No.	Part Description	FG Tag No	Total Net Weight (kg.)	Total Qty (PCS)	Case Tag No	Location	Weight/PCS (kg.)	Qty (PCS)	Net Weight (kg.)
1	FA6690/7858/7859-O	0.9 x 48.2 x Coil [PLATE H/CORE]	F20240804001	1883.98	14	R20240730120	HMT-RC01	134.57	7	941.99
2	FA6690/7858/7859-O	0.9 x 48.2 x Coil [PLATE H/CORE]	F20240804002	1587.96	12	R20240730127	HMT-RC01	132.33	6	793.98
3	FA6690/7858/7859-O	0.9 x 48.2 x Coil [PLATE H/CORE]	F20240804003	1317.1	10	R20240730128	HMT-RC01	131.71	5	658.55

Note :

F20240804001 : R20240730120-1, R20240730120-2, R20240730120-3, R20240730120-4, R20240730120-5, R20240730120-6, R20240730120-7

F20240804002 : R20240730127-1, R20240730127-2, R20240730127-3, R20240730127-4, R20240730127-5, R20240730127-6

F20240804003 : R20240730128-1, R20240730128-2, R20240730128-3, R20240730128-4, R20240730128-5

Checker
TTV SUPPLYCHAIN CO., LTD. (TTV)